50

DART AEROSPACE LTD	Work Order:	 19984
Description: Bearpaw Kit (48" x 19") 205/430	Part Number:	K10015
<b>Dwg:</b> D2521 Rev. H	Qty:	Kits (
<b>Ref:</b> K10015 Rev. A		Page 1 of 1

Step	Location	Procedure	Ву	Date	Qty
1	DC	Issue Traveler	10		
		Note: (1) K10015 Kit consists of Qty (2) D2521	DX	03.11.24	511
		Dwg not required	<i>' []</i> _	,,,,,,,,,,	¢ ,
2	DC	Photocopy bluefile: K10015	10	10 111 11	<b>&gt;</b>
		D205-564-011 D430-688-011	976	<del>11 111 - 11</del>	76
		and create labels per PPP K10015 CHG002	12A	21101	Kla
		(Bag Bluefiles separately) WK 48	H)	03.11.27	70
3	GA 、	Cut 2 blanks per (1) K10015 Kit	1)1	$\sim$	
		Cut blank: 19.50" x 48.00" x 1.00" thick  Material: Black LIHMW 1"  My 1971 A 1.00" thick	15:15	,	
		Material. Black Of liviv	pD.	04.01.08	10
4	MV		13	01.01.0	10
		Inspect material for defects or damage prior to machining	60	04/01/3	6
5	MV	Machine as per Folio FA222 and Dwg D2521	D.	04/0,/3	16
6	QC2	Inspect parts as they come off the CNC machine	100	04/01/3	16
7	MV	Deburr		/ /	
			(U)	04/01/3	16
8	MV	Form as per Dwg D2521 using bending Jig DT8328	mL	04/02/03	6
9	QC8 & 5	Second inspection	200	04-01-31	6
10	KP	Pick: Packing Kit (Note: D2521 is on the BOM as material			
		from step 3)			
		Qty Part Number Description Batch			
	\	8 D2182B055 Rubber Cushion <u>B19540</u>			
	Y	16 D2274 Radius Block <u>B19599</u> 2 D2521 Bearpaw B10984			
		2 D2521 Bearpaw BIG984 16 D2529 Washer BI9786		04.02.62	j
		8 D2947 Clamp 819/06 - B17747	me	04.02.67	a
	j	16 AN4-15A Bolt m 13 437 m/4115	TO PAY		
	ì	16 AN960JD416 Washer M13719	(V)		
	1	16 MS21042L4 Nut (or -4) M13276			
		1 Paperwork package from Step 2	1		
11	QC4	Inspect Kit for 100% Completeness on the W/O	<del>///</del>	-1	<del></del>
			W/	64-02-03	6
12	PK	Identify and pack for shipping as per PPP K10015	Me	04-02-03	6
13	AC	Cost / part 401.1Z	500	04.0Z.04	6
14	DC	Close W/O 3 8750	Ü	04.02.05	
		Inspect Level 21	7,*	04.02,05	6

Rev	Date	Change	Revised By	Approved
Α	01.10.16	K10015 created for Bearpaw Kit (MPP 2164)	SM	A
В	03.05.26	Reformat; Incorporated D2521	KJ/RF	

BB04-02-04, DD.



## **Dart Aerospace Ltd**

Work Order:		WORK ORDER CHANGES						
DATE STEP		PROCEDURE CHANGE			Date	Qty	Approval Manuf / Design Mgr	Approval QC Inspector
NCR		VAIC	ORK ORDER NON-CONFOR	MANCE				
			ORK ORDER NON-CONFOR					
DATE	STEP	Description of NC section A	Corrective Action Section B Intial	Sign & Date		cation tion C	Approval Design Mgr	Approval QC Inspector
								i i
		PAR#:	Fault Category:	DQ/	A:		Date:	<del></del>
				0.4. 11/0.01		,	Data	

NOTE: Date & initial all entries H:Admin-QA\ISO\forms\w/oncB.doc

QA: N/C Closed: \_\_\_\_\_ Date:\_\_\_

## Job Costing Report

Dart Aerospace Ltd. Hawkesbury

Nov 19, 2003 03:48 pm

Work Order No : 0019984 Project Name : \*K10015

Project For : WK350 Work Order Type : Main

Main WO Number

House Part Number: \*K10015 Description : Bearpaw Kit

Manufactured : Yes

Amount Req'd: 5 10 4
Amount Done: 0

Amount Done : 0
Start Date : 11-19-03

Est Finish Date : 12-11-03 Act Finish Date :

Drawings Reqd : No Ok for Approval : Approval Rec'd :

Department Code:

Burden Flags : NNNNNNN WO Status : Open

Invoice State : Not Invoiced

Invoice Date :

Invoice Number :

Invoice Amount: 0.00

Order Entry No :

OE Value : 0.00

Est Margin : 0.000% Actual Margin : 0.000%

\$0 Posted to Finished Goods

		Estimated	Actual	Var. %	Posted	To Post
Material Cost	:	0.00	0.00	0.00	0.00	0.00
Engineering Hours	:	0.00	0.00	0.00		
Engineering Cost	:	0.00	0.00	0.00	0.00	0.00
Production Hours	:	0.00	0.00	0.00		
Production Cost	:	0.00	0.00	0.00	0.00	0.00
Packaging Hours	:	0.00	0.00	0.00		
Packaging Cost	:	0.00	0.00	0.00	0.00	0.00
OverHead Hours	:	0.00	0.00	0.00		
OverHead Cost	:	0.00	0.00	0.00	0.00	0.00
CNC Hours	:	0.00	0.00	0.00		
CNC	:	0.00	0.00	0.00	0.00	0.00
Misc. Hours	:	0.00	0.00	0.00		
Misc.	:	0.00	0.00	0.00	0.00	0.00
		========	=======	======		
Burden	:	0.00	0.00	0.00		
		========	========	======		
Total Cost	:	0.00	0.00	0.00		
Margin	:	0.000	0.000			
Selling Cost	:	0.00	0.00			

Estimated Actual Labour Hrs/Amount Done : 0.00 0.00 Profits/(Loss) 0.00 0.00

DART AEROSPACE LTD	Work Order:	19984	
Description: Bearpaw	Part Number:	D2521	
Inspection Dwg: D2521 Rev: H		Page 1 of 1	

## FIRST ARTICLE INSPECTION CHECKLIST

X First Article Prototype

Inspection Sheet Drawing Dimension		Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
A	1.000	+/-0.030	1 612				
$\frac{A}{B}$	5.600	+/-0.030	12017				
c	11.500	+/-0.030	76/0				
	10.250	+/-0.030	11,000			-	
E	13.250	+/-0.010	10 hall				
F	8.500	+/-0.010	13				
G	22.125		3				
Н		+/-0.030	20/2/2	1	<del></del>	"	
	8.75	+/-0.010	2000				
<u> </u>	44.500	+/-0.030	1120				
J	6.688	+/-0.030	8.65	~			
K	5.625	+/-0.030	Dolde	1/			
L	7.000	+/-0.030	7.05	<u> </u>			
M	5.000	+/-0.010	5:00	<i>i</i> /			
N	4.000	+/-0.030	3.935	E-			
0	6.625	+/-0.030	60000				:
Р	19.000	+/-0.030	19.UD)	1	48.81		
Q	0.31 x 45°	+/-0.030	,30				•
R	0.19 x 45°	+/-0.030	200	<u></u>			
S	0.50 x 45°	+/-0.030	1510	V			
Т	0.38 x 45°	+/-0.030	1390				
U	0.063 x 45°	+0.030/-0.010	,065	<i>i /</i>		`	
V	Ø0.260	+0.005/-0.000	261				
W	Ø0.93	+/-0.030	, 25	1/			
Х	0.30	+0.030/-0.010	,305	1/			
Y	0.375	+/-0.010	377				
Z	0.750	+/-0.030	,7202				
AA	0.250	+/-0.010	218	1/			
AB	4.000	+/-0.030	3,981	1/			
AC	6.625	+/-0.030	(00 GHD	1			
AD	0.950	+0.030/-0.010	e 960	i/			
AE	0.375	+/-0.010	385	1			
AF	3.399	+/-0.030	22/11	1/	1		
AG	6.625	+/-0.030	663				

Measured by:	Audited by:	Prototype Approval:	N/A ···
Date: 04/02/24	Date: 04/0/31	Date:	
	L / \		

Rev	Date	Change	Revised by	Approved
Α	03.09.22	New Issue	KJ/RF	d

H	ELEAS	ED
1	04.01.1	5